

*Sunny -*

Image  
2816

APR 26 2004  
U.S. PATENT & TRADEMARK OFFICE  
42

TRANSMITTAL LETTER (General - Patent Pending)		Docket No. NL 000586
--	--	-------------------------

In Re Application Of: Van Wershoven

Serial No.  
10/022,124

Filing Date  
October 30, 2001

Examiner  
H. Nguyen

Group Art Unit  
2816

Title: INTEGRATED CIRCUIT WITH OUTPUT DRIVERS


TO THE DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE:

Transmitted herewith is: Amendment in 7 pages

1 Drawing Replacement Sheet  
2 Return Receipt Postcards

in the above identified application.


- No additional fee is required.  
 A check in the amount of \_\_\_\_\_ is attached.  
 The Director is hereby authorized to charge and credit Deposit Account No. 500999  
as described below.  
 Charge the amount of \_\_\_\_\_  
 Credit any overpayment.  
 Charge any additional fee required.

  
\_\_\_\_\_  
Signature

Dated: March 30, 2004

John A. Merecki  
Reg. No. 35,812  
Hoffman, Warnick & D'Alessandro LLC  
Three E-Comm Square  
Albany, New York 12207  
(518) 449-0044

I certify that this document and fee is being deposited  
on 04/21/2004 with the U.S. Postal Service as  
first class mail under 37 C.F.R. 1.8 and is addressed to the  
Director of the United States Patent and Trademark Office,  
P.O. Box 1450, Alexandria, VA 22313-1450.

  
\_\_\_\_\_  
Signature of Person Mailing Correspondence

Beverly Kehoe Shea  
Typed or Printed Name of Person Mailing Correspondence

CC:



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant: VAN WERSHOVEN

Atty. Docket: NL 000586

Serial No. 10/022,124

Group Art Unit: 2816

Filed: October 30, 2001

Examiner: H. NGUYEN

Title: INTEGRATED CIRCUIT WITH OUTPUT DRIVERS

Mail Stop Non-Fee Amendment

Commissioner for Patents

PO Box 1450

Alexandria, VA 22313-1450

AMENDMENT

Introductory Comments

In response to the Office Action dated January 21, 2004,  
please amend the above-referenced application as follows:

Amendments to the Drawings

Please accept the attached replacement sheet containing amended FIG. 1, which has been amended to correct the location of the lead line of the "Vssq contact" 6.